

Sail Service di Mario Berlati – Viale dei A. Vecchi, 70 - 48100 Marina di Ravenna - P.IVA 02085750392 Tel. +39-0544-530126 - Fax +39-1782283844 - E-mail: info@sailservice.it - website: www.sailservice.it

"Rimar 36" Bowsprit installation



On this Rimar 36, the bowsprit was installed in a way that the forepeak's entrance could stay clear. This way, the bowsprit could stay on even during a sailing cruise or when you would like to anchor.

On this sailing boat, the installation was made thanks to a custom-made ring bracket inserted into the left bow roller.

The bowsprit's backhead was fixed thanks to a specific plate, as you can see from the images below.



Stern fastening system with aluminum support plate



Stern view



Detail of the ring bracket mounted inside the bow roller